

Leslie Heppler < lheppler@utah.gov

7098

Draft Comments - M/035/0051

1 message

Leslie Heppler heppler@utah.gov

Tue, Feb 9, 2016 at 2:29 PM

To: Sam Smith <sam@ralphsmithco.com>

Cc: Dave Bezzant < DBezzant@avenueconsultants.com>, Paul Baker < paulbaker@utah.gov>

The attached review is a **draft** copy of the OGM review of your latest submittal. The edited copy of the review will be finalized, signed and sent out as soon as possible. Certain portions of the review are incomplete at this time, due to either lack of information, incomplete information, or inconsistent data in the NOI.

It is the goal of OGM to send out the most thorough and detailed review possible as per R647-4-101. 1.

If you have any further questions please don't hesitate to call me at 801-538-5257 thx-lah

Utah Division of Oil, Gas & Mining Office hours - Mon thru Fri 8-5 (801) 538-5340 Leslie Heppler Iheppler@utah.gov Direct line (801) 538-5257 (Mon -Thur)

Thank you for reading this electronic correspondence. Please consider the environment before printing.

REV1-7092-01212016.doc 214K

February 9, 2015

Sam Smith Utah Sand & Gravel LLC 847 West 500 South West Bountiful, UT 84087

Subject: Initial Review of Notice of Intention to Commence Large Mining Operations, Utah Sand &

Gravel, North Salt Lake Mine, M/035/0051, Utah County, Utah

Dear Mr. Smith:

The Division of Oil, Gas and Mining has reviewed the referenced Notice of Intention to Commence Large Mining Operations (Notice) which was received January 11, 2016. The attached comments will need to be addressed before tentative approval may be granted.

The comments are listed under the applicable Minerals Rule heading; please format your response in a similar fashion. Please address only those items requested in the attached technical review by sending replacement pages for the original Notice using redline and strikeout text. After the notice is determined technically complete, the Division will ask that you submit two clean copies of the complete Notice. Upon final approval, both copies will be stamped approved and one will be returned for your records.

Please submit your response to this review by March 11, 2016.

The Division will suspend further review of the Notice until receiving your response to this review. Please contact the lead for this project Leslie Heppler, at 801-538-5257 or me at 801-538-5261 if you have questions about the review or if you would like to schedule a meeting to discuss the comments. Thank you for your cooperation in completing this permitting action.

Sincerely,

Paul B. Baker Minerals Program Manager

PBB: lah:eb Attachment: Review SHPO Letter

cc: lynn.pace@slcgov.com wayne.mills@slcgov.com jasisson@slco.org, Mike George, DWQ (mmgeorge@utah.gov) – fws missing O:\M035-SaltLake\M0350051-NorthSaltLakeLMO\draft\REV1-7092-01212016.doc

Initial REVIEW OF NOTICEOF INTENTION TO COMMENCE LARGE MINING OPERATIONS

Utah Sand & Gravel LLC North Salt Lake LMO

M/035/0051 February 9, 2016

General Comments:

Comment #	Sheet/Page/ Map/Table #	Comments	Initials	Review Action
1	General	The Notice should be formatted to easily incorporate additional revisions and amendments. It is the recommendation of the Division to change "Utah Sand & Gravel" to the "Operator"	lah	
2	General	The Division will have additional comments based on the responses to this review. Please attempt to provide a complete, technically adequate submittal.	lah	
3	Omission	Please submit documentation that Cultural Resource Survey (CRS) has been submitted under the small mine application	lah	
4	Cover sheet	Please add the Permit ID to cover sheet.	lah	
5	Table of Content	Table of Content lists need to account for the Appendices under the sub-consultants reports and reference plates and secondary figures. As written photographs are shown in Appendix I, but in the permit the photographs referenced are actually in Appendix II, figure A2.	lah	
6	Binder	Mining plans are dynamic and need to be updated as plans change by using an MR-REV form. Please submit all future plans in 3 ring binders that can be easily and cost effectively updated without re-submittal of entire document.	lah	
7	Appendix III	The Geotechnical Investigation could not be properly reviewed for the following reasons: a) Plate A-1b is not readable, b) Plate A-1a does not show simple geomechanical properties such as strike and dip or enough of the surrounding geology, c) Report is listed as an "Updated Geotech" Investigation and this is the first geotech report for the permit, d) Executive summary does not match request for a variance R647-4-112, e) Groundwater section does not adequately address groundwater conditions, f) It is unclear why geochem samples were included in the Geotechnical report, perhaps re-title the Geotechnical and Geochemical Report g) Executive summary notes a factor of safety of 1.5, yet only 2 runs show a FOS of 1.349 h) As shown, all geochmechanical data was taken from the fault zone and doesn't represent rock characteristics away from the fault. i) Plates D-1 & D-2 note "none" for water surface, does not include either the Qpc or the Md as shown on the geologic map, location of sections are not shown on a plane view map, j) there is no subsurface data and no data was collected from the outcrops above the floor of the pit k) typo (DOGAM). A geotechnical report is only required for a variance and no variance was requested. If the Operator decides to request a variance a detailed review will be done of the geotech report.	lah	

R647-4-104 - Operator Information and Surface and Mineral Ownership

Initial Review Page 3 of 11 M/035/0051 February 9, 2016

Comment #	Sheet/Page/ Map/Table #	Comments	Initials	Review Action
8	Page 4	2. Operator - Missing physical person. Specifically the person that will have signatory authority. As a courtesy by the Division this review was addressed to Sam Smith. Please add the name of the person who will have the signatory authority.	lah	

R647-4-105 - Maps, Drawings & Photographs

General Map Comments

Comment #	Sheet/Page/ Map/Table #	Comments	Initials	Review Action
9	All Maps	All maps – Please change the text scale from a written description to a bar scale.	lah	

105.1 - Topographic base map, boundaries, pre-act disturbance

Comment #	Sheet/Page/ Map/Table #	Comments	Initials	Review Action
10	Figure 1	Add the number of acres to the property boundary box.	lah	
11	Figure 2	"North Salt Lake Mine" is listed as an "adjacent mine", please remove the North Salt Lake Mine from the Legend block and simply label the map and remove the shaded yellow highlighted square	lah	
12	Figure 2	Identify the type of utility, include basic information on the type of utility, such as 320 KW power line or buried 72" pipe	lah	
13	Page 7 Para 1	Rewrite the last sentence: as OGM does not "engage" between the utility owner and the Operator. It is the Operators responsibility to comply with R647-1-102.3	lah	

105.2 - Surface facilities map

Comment #	Sheet/Page/ Map/Table #	Comments	Initials	Review Action
14	Figure 4	Use a newer base map and add a list and description of the facilities. This will tie to the bond calculation sheets and be utilized in bond releases.	lah	
15	Figure 4	Include growth medium stockpile	lah	

105.3 - Drawings or Cross Sections (slopes, roads, pads, etc.)

Comment #	Sheet/Page/ Map/Table #	Comments	Initials	Review Action
16	Page 7 & Figure 5	Section 105.3 Reclamation Activities, refers to Figure 5 for reclamation activities. This map in all reality only shows final contours. A reclamation map is needed showing the various reclamation activities and treatments that will be used throughout the site, such as regrading, topsoil replacement (different depths) seeding methods, etc.	lk	
17	Figures 5, 6, & 7	Cross Sections are incomplete and do not follow text. At a minimum show actual location of the section on the plane view maps, include lines that delineate pre mining, during mining and final reclaimed slopes. Cross sections must match text. Do not use vertical exaggeration.	lah	

Initial Review Page 4 of 11 M/035/0051 February 9, 2016

Comment #	Sheet/Page/ Map/Table #	Comments	Initials	Review Action
18	Omission	Provide a SWPPP map to show how surface runoff will be managed and protective of downstream receptors.	mpb	
19	Figure 5	There is a cross section listing in the legend with no symbol and no cross section location lines on the map. Please show A-A' and B-B' lines on the map.	mpb	
20	Figure 5 & page 7 para 2	As shown on figure 5 and the cross sections the pits lowest elevation will be 4270'. If that is the intent of the operator, the text will need to reflect the design.	lah	

105.4 - Photographs

Comment #	Sheet/Page/ Map/Table #	Comments	Initials	Review Action
21	Omission	It is the recommendation of the Division to include photographs for future documentation. It is the recommendation of the Division to bring both figure B1 and B2 from Appendix B of Appendix II into the NOI	lah	

105.5 - Underground & 105.6 - Other maps

Comment #	Sheet/Page/ Map/Table #	Comments	Initials	Review Action
22	Page 7. Para 7 &	Paragraph 7 regarding figure 7 should be moved to section 105.3. There is no section 105.6 in R647-4, paragraph 8 should be moved to section 105.3	lah	
23	Page 8 Para 2	Paragraph 2 regarding the geologic map should be moved to section 105.3. In addition Figure 9 is incomplete, for the same reasons noted above concerning the geologic maps in the Geotechnical report. In additional the faults were left off of this map.	lah	

R647-4-106 - Operation Plan

General Operation Comments

Comment #	Sheet/Page/ Map/Table #	Comments	Initials	Review Action
24		Due to the lack of information with the cross sections, more questions could be generated regarding the Operation Plan.	lah	

106.1 - Minerals mined

Comment #	Sheet/Page/ Map/Table #	Comments	Initials	Review Action
25	Page 8, para 3	Rewrite last sentence as topsoil is to be used on site for reclamation purposes.	lah	

106.2 - Type of operations conducted, mining method, processing etc.

Initial Review Page 5 of 11 M/035/0051 February 9, 2016

Comment #	Sheet/Page/ Map/Table #	Comments	Initials	Review Action
26	Page 8	Text notes a specific contractor will be used for blasting, it is the recommendation of the Division to refer to the "Blasting contractor"	lah	
27	Page 8	More info is needed on the interview with Blasting Consultant as a reference.	lah	
28	Page 8	Based on cross section submitted it will be difficult to hold a 70 degree slope without pre-splitting. In other words, the 20 foot bench noted in the text could lose integrity. More information is needed.	lah	

106.3 - Estimated acreages disturbed, reclaimed, annually

Comment #	Sheet/Page/ Map/Table #	Comments	Initials	Review Action
29	Page 9 para 2	22.92 acres is noted, but none of the maps show any activity in the southern triangle.	lah	

106.4 - Nature of materials mined, waste and estimated tonnages

Comment #	Sheet/Page/ Map/Table #	Comments	Initials	Review Action
30	Page 9	More information is needed regarding annual production estimates	lah	

106.5 - Existing soil types, location, amount

Comment #	Sheet/Page/ Map/Table #	Comments	Initials	Review Action
31	Page 9	The soil data provided is incomplete. Please provide results for the following additional parameters: Texture, pH, EC (conductivity), Percent Organic Matter, CEC (cation exchange capacity), Phosphorus (as P ₂ O ₅), and Potassium (as K ₂ O).	lk	
32	Page 10	2-15 feet of soil material is not considered 'relatively thin'. For just the 12 acres of undisturbed area, this results in a range of 38,720 to 290,400 cubic yards of soil. This is considered a significant amount and plans to salvage and stockpile topsoil for reclamation needed (see R647-4-106.6)	lk	u u u b s s s

106.6 - Plan for protecting & re-depositing soils

Comment	heet/Page/ Map/Table #	Comments	Initials	Review Action
---------	------------------------------	----------	----------	------------------

Initial Review Page 6 of 11 M/035/0051 February 9, 2016

Comment #	Sheet/Page/ Map/Table #	Comments	Initials	Review Action
33	Page 10	Just because the topsoil is 'relatively thin' is no reason for not salvaging and stockpiling the topsoil for future reclamation purposes. Please provide plans to salvage and stockpile all topsoil, including locations of topsoil stockpiles, volumes of soil to be in each stockpile, and how soil stockpiles will be protected from erosion and further impacts.	lk	
		Provide plans on how soil materials will be redistributed at the time of reclamation, including type(s) of equipment to be used, depth of soil replacement (it is recommended that a minimum of 12 inches be replace) and amendments/fertilizer that may be needed (to be determined after all soil analytical data is provided).	lk	
		If other material is to be used as a substitute soil, then a complete analysis for that material is needed as well, including: Texture, pH, EC (conductivity), SAR, Percent Organic Matter, CEC (cation exchange capacity), Total Nitrogen, Nitrate Nitrogen, Phosphorus (as P ₂ O ₅), and Potassium (as K ₂ O). The ratio of this material and the topsoil is needed, or if topsoil will be used in one area and the substitute materials used on another area, it needs to be identified on the reclamation map. Assuming the soil depth of 2-15 feet is correct, there should be sufficient soil material for reclamation of the entire site.	lk	

106.7 - Existing vegetation - species and amount

Comment #	Sheet/Page/ Map/Table #	Comments	Initials	Review Action
34	Page 10	Please provide data showing the %ground cover of vegetation at the site. This data is missing from this section as well as the SWCA report	lk	
35	Page 10	The last paragraph on this page identifies 5 state listed and 2 county listed noxious weeds occurring onsite. The last sentence states that "if pervasive weed growth occurs, a management plan will be set it place." Given the invasive nature of noxious weeds, a weed control plan needs to be developed and implemented ASAP. Noxious weed infestations can negatively affect establishment of a permanent, diverse vegetation community that is of utility for the post-mining land use, and can delay release of reclamation surety by several years. Note, the SWCA report also recommends a weed control plan for the noxious weeds.	lk	

106.8 - Depth to groundwater, extent of overburden, geology

Comment #	Sheet/Page/ Map/Table #	Comments	Initials	Review Action
36	Page 11	Statement says there is "no groundwater detected" but does not specify to what depth. A review of Division of Water Rights information should indicate the depths to groundwater for nearby wells. Please provide a local depth to groundwater.	mpb	
37	Omission	Please show the locations of the wells used to identify groundwater depths on one of the existing maps.	mpb	

Initial Review Page 7 of 11 M/035/0051 February 9, 2016

Comment #	Sheet/Page/ Map/Table #	Comments	Initials	Review Action
38	Page 11 Para 3	Regional structural geology is discussed in the text and the geologic maps do not show enough localized geology of the mine area. The geologic maps and text needs to be relevant to the mine site and the permit. Additional comment can be generated in future reviews, based on future submittals.	lah	

106.10 - Amounts of material moved (including ore, waste, topsoil, etc.)

Comment #	Sheet/Page/ Map/Table #	Comments	Initials	Review Action
39	Page 11	More information is needed based on submittals of new cross sections.	lah	
40	Page 11	No information is included on waste piles or topsoil piles	lah	

R647-4-109 - Impact Assessment

109.1 - Impacts to surface & groundwater systems

Comment #	Sheet/Page/ Map/Table #	Comments	Initials	Review Action
41	Incomplete	Impacts to both surface and groundwater systems cannot be determined due to a lack of information provided. At a minimum, please provide the map from the SWPPP for the site as described previously, and depths to groundwater obtainable from the Utah Division of Water Rights, with a map showing the well locations from which the data was obtained.	mpb	

109.2 - Impacts to threatened & endangered wildlife/habitat

Comment #	Sheet/Page/ Map/Table #	Comments	Initials	Review Action
42	Page 12	Waiting for final IPAC report to make comments on this section	lk	

109.3 - Impacts on existing soils resources

Comment #	Sheet/Page/ Map/Table #	Comments	Initials	Review Action
43	Page 12	This section does not discuss impact to the soil resources (past and future), such as volume of material, nature of impacts or the extent of impact (spatially or in time), nor does it provide a discussion of plans to mitigate these impacts (refer to R647-4-109.5).	lk	

109.4 - Slope stability, erosion control, air quality, safety

Comment #	Sheet/Page/ Map/Table #	Comments	Initials	Review Action
44	Omission	Provide a SWPPP map so the Division can evaluate methods and technologies to be used to manage erosion and sediment control.	mpb	

Initial Review Page 8 of 11 M/035/0051 February 9, 2016

Comment #	Sheet/Page/ Map/Table #	Comments	Initials	Review Action
45	Page 13 para 1	Please note comments above relating to the Geotechnical report. In addition the report needs to include a discussion on bedding plane failures.	lah	
46			lah	

109.5 - Actions to mitigate any impacts

Comment #	Sheet/Page/ Map/Table #	Comments	Initials	Review Action
47	Omitted	See comments under 109.3	lk	
48	Omission	Include a statement under section 109.5 on the "actions to mitigate". Please feel free to reference section 109.1 thru 109.4, but each potential impact needs to discuss the mitigation of the impacts listed above under 109.	lah	

R647-4-110 - Reclamation Plan

110.1 - Current & post mining land use

Comment #	Sheet/Page/ Map/Table #	Comments	Initials	Review Action
49	Page 13	While Utah Sand and Gravel may not have post-mining plans for the property, there still will be a use of the property. If light manufacturing is not viable at the end of mine life, the operator is expected to reclaim the area to open space, which would require the removal of all facilities and structures, eliminating any public safety or environmental hazards, and establishing a diverse, perennial vegetative cover to stabilize and control erosion. Note, most of the above is discussed somewhere in the NOI, but should be at least summarized in this section.	lk	
		In addition include a discussion in the text regarding the post mining land use of the hillside versus the pit floor.	lah	

110.2 - Roads, highwalls, slopes, drainages, pits, etc., reclaimed

Comment #	Sheet/Page/ Map/Table #	Comments	Initials	Review Action
50	Page 13	(see comments under 106.6) Please describe how soil materials and seeding will take place with 100-foot lifts and 20-foot wide benches. Will there be access to the benches with equipment at the end of mine life, or will there be on-going reclamation before benches are abandoned to replace topsoil and revegetate?	lk	9/4
51	Page 14	The NOI states "Highwall berms will be left along those portions of the highwall and sidewall rim that are over five feet high". Is this referring to the height of the berm, or the height of the highwall and side wall rims? If referring to the height of the berm, this would leave the berm approximately 15 feet wide, which does not leave sufficient room for seeding equipment. Also, what is the volume of material needed to construct the berms, and where will it come from?	lk	

Initial Review Page 9 of 11 M/035/0051 February 9, 2016

Comment #	Sheet/Page/ Map/Table #	Comments	Initials	Review Action
52	Page 13-14	As written the text notes a 1H:1V slope angle, this does not match text elsewhere in the plan or the cross sections. In addition the plan commits to a 45 degree average slope, which is not possible based on the rest of the plan.		

110.3 - Description of facilities to be left (post mining use)

Comment #	Sheet/Page/ Map/Table #	Comments	Initials	Review Action
53	Page 14 Para 3	Post mining land use is noted under section 110.1	lah	

110.5 - Revegetation planting program

Comment #	Sheet/Page/ Map/Table #	Comments	Initials	Review Action
54	Page 14	A revegetation planting plan is needed to establish a permanent, diverse vegetation cover capable of supporting the post mining land use. At a minimum, this plan needs to include seedbed preparation (including any amendments and/or fertilizers that may be needed, based on the soil analysis), timing of seeding (late fall is best), an acceptable seed mix including seeding rates, seeding method(s) (i.e. drilling, broadcasting, aerial seeding, etc), and the use of mulch (type and rate) as appropriate or needed. Since there are already noxious weeds on-site, a weed monitoring and control plan should also be provided for the post-reseeding time that would be in place until the revegetation standard is met and the site is released.	lk	
55			lk	
56	Page 15	The proposed seed mix is not acceptable. As is, it is unlikely that a permanent, diverse vegetative cover would establish. The weedy species (Broom Snakeweed, Common Ragweed, and curlycup Gumweed) needs to be eliminated. Also, it is unlikely you will establish any Gambel Oak from seed, especially at the proposed seeding rate of 0.02 lbs. per acre. If you desire to establish Gambel Oak, please consider using transplant stock. Seeding rates of other species need to be adjusted. Seeding rates very tiny-seed species needs to be decreased and the seeding rates for the most of the larger-seed species needs to be increased. Other species such as Wyoming big sage, Palmer penstemon, Forage kochia, should be added. Attached is a seed mix for your consideration. If acceptable, please include in the NOI. Otherwise, you will need to develop a different mix than the one currently proposed in your NOI.	lk	
57	Page 14	It is unclear what the proposed post mining reclamation plan is, please submit a map for bonding purposes, which will show the areas to be top soiled and seeded. (include depths, etc.)	lah	

Initial Review Page 10 of 11 M/035/0051 February 9, 2016

R647-4-112 - Variance (List all variances requested and make a finding if approving.)

Comment #	Sheet/Page/ Map/Table #	Comments	Initials	Review Action
58	Omitted	If the existing topsoil is not salvaged and stockpiled for reclamation, then a variance needs to be requested. The request needs to identify the appropriate rule for which it is being requested, a detailed description of the variance being requested, and an alternative plan that demonstrates that the intent of the rule for which the variance is being requested will be achieved.	lk	
59	Omission	No variance has been requested for highwalls, which is contrary to cross sections and text	lah	

R647-4-113 - Surety

Comment #	Sheet/Page/ Map/Table #	Comments	Initials	Review Action
60	Cash Surety	All operators that want to provide a cash surety must also provide an accurately completed IRS Form W-9 with their cash deposit. The bank where the State Treasurer will deposit the cash must approve and accept the W-9 prior to the Division granting final approval of the permit.	OGM	
61	Omission	Please provide the backup data for the bond calculation shown on page 14. Use the Divisions bond calculation sheets on our web site at www.ogm.utah.gov	lah	
62	Page 15	Text indicate phase 1, but there is no other reference in the text to phase 1. Please make the text consistent throughout the NOI.	Please lah	
63	Omission	Appendix F is missing – In the mean time, while this permit is being reviewed, please submit the additional \$870,158 (based in the consultants estimate) until the permit has been completed and approved. Please see page 15 for consultant estimate.	lah	

Attached: Recommended Seed Mix

Initial Review Page 11 of 11 M/035/0051 February 9, 2016

Recommended Revegetation Species List for

Utah Sand and Gravel North Salt Lake Mine M/035/0051

Common Name	Species Name	*Rate lbs/ac (PLS)
Intermediate wheatgrass	Agropyron intermedium	2.0
Western wheatgrass	Agropyron smithii	2.0
Bluebunch wheatgrass	Agropyron spicatum	2.0
Sandberg bluegrass	Poa Secunda	0.1
Sheep fescue	Festuca ovina	0.25
Western yarrow	Achillea millefolium	0.1
Common Sunflower	Helianthus annuus	1.0
Ladak alfalfa	Medicago sativa	1.0
Yellow Sweetclover	Melilotus officinalis	0.5
Palmer penstemon	Penstemon palmerii	0.5
Lewis flax	Linum lewisii	1.0
Pacific aster	Aster Chilensis	0.1
Wyoming big sagebrush	Artemisia tridentata wyomingensis	0.1
White stem rabbitbrush	Chrysothanmus nauseosus albicali	
Forage kochia	Kochia prostrata	0.5
	Total Seed	11.35 lbs/ac

^{*} Rate is recommended for broadcast seeding methods.